

RUE191041190408 Field Engineering

1 813 893 6420

P-2

AVOID VERBAL ORDER

AUGUST 19/2004

TO : (b)(6), (b) (7)(C)

BE ADVISED THAT SPOT SEWER REPAIR WORK
PERFORMED BY FERGUSON CONSTRUCTION CO
CONTRACTED BY INLAND WATERS POLLUTION
CONTROL **BE STOPPED** UNTIL THE ISSUES OF
RESTORATION FOR THE ATTACHED JOB WORK
SITES BE RESOLVED..

(b)(6), (b) (7)(C)

PRINCIPAL CONSTRUCTION INSPECTOR
DETROIT WATER/ SEWERAGE

**DEFICIENCY LIST / AUGUST 2004
SEWER SPOT REPAIRS...**

1... (b)(6), (b) (7)(C)

LAWN/SOD / CONCRETE DRIVEWAY/FENCE

- SWING SET NEEDS TO BE REPLACED
IT WAS TAKEN AND NOT REPLACED

2... (b)(6), (b) (7)(C)

LAWN/ SCRUBS FENCE

(b)(6), (b) (7)(C)

3... FENKELL/ PIEDMONT ASPHALT REPLACEMENT

4... FENKELL/ WARWICK ASPHALT REPLACEMENT

5... (b)(6), (b) (7)(C) /FENCE POST REMOVAL/MOLDING REPAIR ON
GARAGE

(b)(6), (b) (7)(C) HME. CELL (b)(6), (b) (7)

6... (b)(6), (b) (7)(C) /GRADE AREA/ REPLACE FENCE
(b)(6), (b) (7)(C)7... (b)(6), (b) (7)(C) /SINK HOLE/ CONCRETE DRIVEWAY REPLACED.
(b)(6), (b) (7)(C)8... GRANDVILLE/ GRAND RIVER CONCRETE ALLEYWAY
REAR OF DOCTORS OFFICE
DPW COMPLAINT R/W INSPECTOR 224-39359... (b)(6), (b) (7)(C) / ASPHALT CRACKED NEEDS SEALANT
APPLIED TO DRIVEWAY
(b)(6), (b) (7)(C)10... (b)(6), (b) (7)(C) / FENCE REPLACEMENT
(b)(6), (b) (7)(C)11... LENOX @ DICKERSON
STOCKPILED STONE NEEDS REMOVAL12... BALDWIN @ GOETHE
CONCRETE ALLEY REPLACEMENT13... MACK AVE @ McCULLAN
CONCRETE ALLEY REPLACEMENT
BEHIND /PARTY STORE

14. (b)(6), (b) (7)(C)

GRASS AND GROWINGS WERE PLANTED
WET SPOT IN BACK YARD.